

## City of Markham Case Study

A Municipal point of view and challenges to identify and rectify cross bores







# Storm Sewer Condition Assessment

### **Project Team**

- Robert Muir, M.A.Sc., P.Eng.
  - Manager, Stormwater (AM Department)
- Philip Zhang, P.Eng.
  - Engineering Design Assistant (AM Department)
- Robert Marinzel, C.E.T.
  - Technical Coordinator (Operations)
- Tanya Stephens, A.Sc.T., GIS (pg)
  - TDS Consulting, NASSCO Trainer








# Storm Sewer Condition Assessment

CCTV contracts help determine the internal condition of pipe by reporting observed defects in a standard coding method. Codes are recorded to capture defect type, severity, and length of occurrence.


#### Deliverables:



Video File



Database (.mdb)



Report (.pdf)








# Storm Sewer CCTV Contract

• 2012-2014 CCTV (7 year cycle)

2367 of 16306 pipes inspected (15%)











# Storm Sewer CCTV Contract

 NASSCO's Pipeline Assessment Certification Program (PACP) standard

OBI condition grade 5



Damage (holes) must also be coded and report cross bores immediately!








### **Grade 5 Defects**

### Prioritize using PACP Quick Rating


**Courtesy of NASSCO** 

- OBI
- X
- D
- HSV / HVV
- BSV / BVV
- DI
- SRP / SRC / SMW
- IG
- Blockages >30%
- MWLS >75%


















# **Decision Making Process**







- Operations
- Maintenance
- Work Orders
- O&M Budget





- Database
- GIS
- Criticality/Priority/Risk



• Repair/Replace








# Storm Sewer Asset Management

- 6 potential cross bores found
- \$500,000 annual repair budget













# **Decision Making Process**



**RISK TO PUBLIC SAFETY AND THE ENVIRONMENT TOO HIGH!** 







## **Rectifying Cross Bores**


City of Markham




Consultant

Field survey to identify ownership







Utility

- Removes cross bore
- restores disturbed areas
- repairs original pipe with approved method and contractor

BLUE represents costs to the City that are not necessarily budgeted. Unanticipated projects, regardless of scope, require administration and project management.







### **Lessons Learned**

#### QA/QC of CCTV data

- Communication with contractor regarding immediate reporting of grade 5 defects.
- Data review for efficient decision making.
- In-house PACP certification.

#### Further our goals towards Asset Management

- Create a data repository.
- Ability to bring issues to the forefront from a single data source.
- Ability to track trends from historical condition data.
- CCTV database link to GIS.
- Criticality and Prioritization Workshop.

### Approval of utility's repair

Utility Reporting to include post rehab CCTV and above ground photographs.







## **Questions?**

## Tanya Stephens, A.Sc.T., GIS (pg)

Email: tdsconsulting@rogers.com

Phone: (416) 616-5521



http://www.linkedin.com/in/stephenstanya



